

Code E91

Error Message E91 may appear for several reasons:

- ✓ **Insufficient salt concentration in the water** → Add salt to the water to the required level as per the instructions in the manual.
- ✓ **Scaling of the cell electrode** → Clean the electrode with vinegar according to the instructions in the manual.
- ✓ **End of electrode life/wear** – This occurs when the hot tub is used intensively or has been in use for a long time, even if the electrodes are clean → The electrode needs to be replaced with a new one.
- ✓ The corresponding part number (electrode/titanium plates) can be found in the manual – it is a 5-digit numerical code (e.g., 11899). The electrode can be ordered as a spare part.
- ✓ **Water temperature** in the hot tub **below 10°C** → Check the functionality of the device at a higher water temperature.



If none of the above steps resolve the issue, it is an electronic problem with the control unit and needs to be repaired by a serviceman/technician.



For more information, visit the INTEX customer support portal
www.intexsupport.com