


O₃ GENERATOR indicator on the ozone & saltwater system



Ideally, this indicator should be off. If on, it indicates a fault of the motor. If the product is still under warranty, you should make a claim at the seller. Otherwise request a replacement control station (motor base).



For more information, visit the INTEX customer support portal
www.intexsupport.com